



# BOAT DISCLOSURE

PURPLE WAVE  
CUSTOMER NO.

THIS DISCLOSURE IS COMPLETED BY THE SELLER.

Seller states that the information contained in this disclosure is correct to the best of Seller's actual knowledge as of this date. A copy of this disclosure may be delivered to prospective buyers.

Date 5-13-09 Make, model 310 S60 Roy Year 1998 ICN No., if any \_\_\_\_\_

	YES	NO	N/A	COMMENTS
What is the vehicle identification number of the vehicle (must match paperwork)?				VIN# _____
Does the boat have a bill of sale or registration that is signed and present with all lien releases present?	X			
Have you provided an ignition key?	X			
Is the check engine or any other trouble light regularly on or have gauges indicated any problems?	X			
Have the oil changes and scheduled maintenance been performed regularly?	X			
Does the engine start well?		X		Pickled
Does the engine idle well?		X		" "
Is the engine performance smooth under acceleration and operation?		X		
Does the vehicle operate without using oil or fluids? If not, approximately how much oil/fluid must be added per day of operation?	X			
Is the vehicle free of abnormal noise (cold/hot and high/low speeds)?	X			
Does the transmission shift without noise or slippage (operational/smooth/ proper shift points)?	X			
Are the steering, rack and pinion and/or steering linkage performance good (steering wheel free of play, steering wheel centers and/or good response)?	X			
Do the electrical systems operate effectively?	X			
Are gauges, speedometer, tachometer and warning lights operational?	X			
Is the trolling motor operational?		X		
Is the boat exterior in good condition, free of holes, dents and/or patched damage (if not, explain defects)?	X			
Does the tilt and trim system work?	X			
Does the stereo system work?	X			
Is the trailer in working condition? and are its tires currently holding air?			X	
Please list any recent repairs, problems and/or other history.				*See attached addendum for additional information
<u>BOAT SANK IN BRUSH WORTER JUST TO TOP OF ENGINE.</u>				
List any special accessories and/or attributes.				
<u>NO BLUETOOTH</u>				

SELLER SIGNATURE: \_\_\_\_\_

Neither Purple Wave, Inc., ("Auctioneer") nor its employees or affiliates warrants or guarantees the accuracy or completeness of this Disclosure or any subsequent disclosures. This Disclosure has been completed by the seller or at the direction of seller and is not intended to be and cannot be used as a substitute for an inspection of auction assets or any other means of investigating an asset's history and condition. It is provided as a courtesy and convenience to interested parties and is based on Seller's current actual knowledge.

THE ASSET DESCRIBED ABOVE WILL BE SOLD SUBJECT TO THE TERMS PUBLISHED AT WWW.PURPLEWAVE.COM ("TERMS"), AND PURSUANT TO THE EXPRESS PROVISIONS OF ANY SEPARATE PURCHASE CONTRACT ("CONTRACT") THAT WINNING BIDDERS ARE REQUIRED TO EXECUTE. THE TERMS AND THE CONTRACT, IF ANY, SHOULD BE READ CAREFULLY BY ANY INTERESTED PARTY. THEY SET FORTH ADDITIONAL IMPORTANT DETAILS THAT WILL CONTROL THE PURCHASE OF THE ASSET DESCRIBED ABOVE. BY REVIEWING THIS DISCLOSURE, ALL INTERESTED PARTIES AGREE THAT HE/SHE/IT: (I) HAS RELIED SOLELY ON HIS/HER/ITS PERSONAL INSPECTION AND THOSE OF HIS/HER/ITS AGENTS AND INSPECTORS WHEN DECIDING TO BID ON THE ASSET; AND (II) HAS NOT RELIED ON THE ACCURACY OR COMPLETENESS OF INFORMATION PROVIDED BY SELLER OR AUCTIONEER, WHETHER ORAL, WRITTEN OR POSTED ON AUCTIONEER'S WEBSITE, NOR HAS HE/SHE/IT ASSUMED OR EXPECTED THAT SELLER OR AUCTIONEER HAVE DISCLOSED ALL INFORMATION THAT COULD BE REASONABLY ASCERTAINED BY INSPECTION OF THE ASSET.

## Addendum to disclosure:

This Yacht took on fresh water in the engine compartment due to an exhaust manifold coupler leak while it was docked without power.

The water never exceeded the top of the engine block.

The engines and generator have manually been turned over since and have been pickled and winterized.

As always Purple Wave recommends that you or your mechanic evaluate all mechanical components prior to bidding.

The outdrives have been removed for transport and will need to be reinstalled when it arrives at its destination.