

7511

INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty	Description	Price	Extension
2037	03/31/05	161463	LABOR	WELD	1.50	FABRICATE BRACKETS AND WELD INTERIOR SHELVES INTO PLACE SO THAT LOAD SHIFTING WILL NOT HAPPEN	45.00	67.50
			SUPPLIES	SS	1.00	Shop Supplies	2.70	2.70
			PARTS	MISC	0.50	WELDING SUPPLIES AND MATERIAL	45.00	22.50
								92.70
2148	05/05/05	163228	A_DIAGNOS	Reported	0.00	TRANS LEAK DRIVERS STATES THAT IN THE AM THE TRUCK SLIPS IN GEAR BUT ONCE WARMED UP IT RUN FINE WE FOUND THE VAN TO BE 4.5 QTS LOW ON FLUID WHEN IT ARIVED ADDED TO FULL THEN CLEANED AND CHECKED FOR LEAKS AFTER 2 HOURS OF TEST DRIVING NO LEAKS WERE FOUND THE PAN WAS MOIST BUT NOT DRIPPING	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	8.65	8.65
			PARTS	B42	1.00	TRANS FILTER KIT	8.15	8.15
			PARTS	51085	1.00	OIL FILTER	7.44	7.44
			PARTS	10001	1.00	OIL ADDITIVE	10.01	10.01
			PARTS	WWS	0.50	WASHER SOLVENT	1.94	0.97
			LABOR	LOF1	0.45	FULL SERVICE OIL CHANGE	45.00	20.25
						- Change Oil - Replace Oil Filter - Lubricate Chassis		
						FOLLOWING ITEMS CHECKED:		
						- Transmission / Transaxle Fluids - Differential Fluid - Brake Fluid - Power Steering Fluid - Window Washer Fluid - Battery Water - Air Filter - Breather Element - Wiper Blade - Tire Pressure		
			PARTS	324	9.00	MAX LIFE TRANSMISSION FLUID	4.09	36.81
			PARTS	AT203	2.00	TRANS ADDITIVE FRICTION MODIFIER	12.31	24.62
			LABOR		1.40	CHANGE TRANSMISSION FLUID & FILTER	45.00	63.00
			LABOR		0.60	DIAGNOSE TRANSMISSION PROBLEM	45.00	27.00
			LABOR		2.00	TEST DRIVE	45.00	90.00
								296.90
2905	12/06/05	172082	A_DIAGNOS	Reported	0.00	IN FOR BRAKES AND SERVICE	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	16.98	16.98
			PARTS	5333	1.00	BRAKE ROTOR	74.32	74.32
			PARTS	MX269	1.00	BRAKE PADS FRONT	57.11	57.11
			PARTS	A16	2.00	WHEEL BEARING OUTER	9.11	18.22
			PARTS	A18	1.00	WHEEL BEARING INNER	11.28	11.28
			PARTS	3087	1.00	SEAL WHEEL BRG	9.22	9.22
			LABOR		2.50	R & R FRONT DISC PADS & REPLACE ROTORS	45.00	112.50

INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty	Description	Price	Extension
2905		172082	LABOR			INSTALL NEW WHEEL BEARINGS AND SEALS		
			LABOR		0.50	INSPECT BRAKES (4 WHEELS)	55.00	27.50
			LABOR		0.10	ADJUST TIRE PRESSURE	55.00	5.50
			LABOR		0.60	CLEAN & ADJUST BRAKES (2 WHEELS)	55.00	33.00
			LABOR		0.80	R & R MIRROR (DOOR MOUNTED) COVERS AND ADJUST TENSION STRAP FOR SWING	55.00	44.00
			LABOR	LOF1	0.45	FULL SERVICE OIL CHANGE	45.00	20.25
						- Change Oil		
						- Replace Oil Filter		
						- Lubricate Chassis		
						FOLLOWING ITEMS CHECKED:		
						- Transmission / Transaxle Fluids		
						- Differential Fluid		
						- Brake Fluid		
						- Power Steering Fluid		
						- Window Washer Fluid		
						- Battery Water		
						- Air Filter		
						- Breather Element		
						- Wiper Blade		
						- Tire Pressure		
			PARTS	51085	1.00	OIL FILTER	7.64	7.64
			PARTS	10001	1.00	OIL ADDITIVE	10.60	10.60
			PARTS	CIT10W30	5.00	10W30 BULK OIL	2.29	11.45
			PARTS	WWS	1.00	WASHER SOLVENT	2.12	2.12
			PARTS	512	2.00	LIGHT BULB	0.76	1.52
			LABOR	LIGHTING	0.50	REPLACE BOTH BRAKE LIGHT BULBS IN CYCLOPSE LIGHT	45.00	22.50
			PARTS	99-19	2.00	WIPER BLADE	14.90	29.80
			LABOR	WINSHEILD	0.50	REPLACE WINSHIELD WIPER BLADES WITH NEW	45.00	22.50
			LABOR	LABOR	1.00	REMOVE DRIVERS DOOR PANEL TO REPAIR LOCK CYLINDER AND SHEET METAL	45.00	45.09
								583.01
3213	02/14/06	175390	LABOR	LOF1	0.45	FULL SERVICE OIL CHANGE	45.00	20.25
						- Change Oil		
						- Replace Oil Filter		
						- Lubricate Chassis		
						FOLLOWING ITEMS CHECKED:		
						- Transmission / Transaxle Fluids		
						- Differential Fluid		
						- Brake Fluid		
						- Power Steering Fluid		
						- Window Washer Fluid		
						- Battery Water		
						- Air Filter		
						- Breather Element		
						- Wiper Blade		
						- Tire Pressure		
			PARTS	CIT10W30	5.00	10W30 BULK OIL	2.29	11.45



INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty Description	Price	Extension
3838	07/14/06	185163	LABOR	LOF1	0.45 FULL SERVICE OIL CHANGE	45.00	20.25
					- Change Oil - Replace Oil Filter - Lubricate Chassis		
					FOLLOWING ITEMS CHECKED:		
					- Transmission / Transaxle Fluids - Differential Fluid - Brake Fluid - Power Steering Fluid - Window Washer Fluid - Battery Water - Air Filter - Breather Element - Wiper Blade - Tire Pressure		
			PARTS	51085	1.00 OIL FILTER	7.25	7.25
			PARTS	CIT10W30	5.00 10W30 BULK OIL	2.43	12.15
			PARTS	WWS	1.00 WASHER SOLVENT	2.27	2.27
			PARTS	10001	1.00 OIL ADDITIVE	12.17	12.17
			SUPPLIES	SS	1.00 Shop Supplies	1.62	1.62
							55.71
3897	07/28/06	186009	LABOR	LABOR	0.80 REPAIR REAR DOOR LINKAGE	45.00	36.00
					THE LINKAGE WAS BENT AND NEEDED STRAIGHTENING		
			SUPPLIES	SS	1.00 Shop Supplies	1.50	1.50
							37.50
4030	09/19/06	0	A_DIAGNOS	Reported	0.00 PREP FOR PAINT	0.00	0.00
			SUPPLIES	SS	1.00 Shop Supplies	11.18	11.18
			FUEL	FUEL	5.00 FUEL	2.50	12.50
			LABOR	LABOR	8.00 REMOVE DOOR HANDLES, LOCK CYLINDERS, BUMPERS, LADDER RACKS, AND DECALS SO THAT THE VAN CAN BE PAINTED. ASSEMBLE VAN AFTER PAINTING AND INSTALL NEW WINDOW BLACK OUTS.	45.00	360.00
							383.68
4360	11/27/06	192567	LABOR	LOF1	0.45 FULL SERVICE OIL CHANGE	45.00	20.25
					- Change Oil - Replace Oil Filter - Lubricate Chassis		
					FOLLOWING ITEMS CHECKED:		
					- Transmission / Transaxle Fluids - Differential Fluid - Brake Fluid - Power Steering Fluid - Window Washer Fluid - Battery Water - Air Filter - Breather Element - Wiper Blade		

INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty Description	Price	Extension
4360		192567	LABOR		- Tire Pressure		
			PARTS	51085	1.00 OIL FILTER	7.25	7.25
			PARTS	CJT10W30	5.00 10W30 BULK OIL	2.62	13.10
			PARTS	WWS	0.50 WASHER SOLVENT	2.27	1.13
			PARTS	10001	1.00 OIL ADDITIVE	11.91	11.91
			SUPPLIES	SS	1.00 Shop Supplies	2.66	2.66
			PARTS	50/50 PRE-MIX	0.50 PRE-MIXED 50/50 ANTIFREEZE	7.69	3.84
			PARTS	99-18	2.00 WIPER BLADE	15.57	31.14
							<u>91.29</u>
4533	02/02/07	194947	A_DIAGNOS	Reported	0.00 CHECK CHARGING SYSTEM	0.00	0.00
			SUPPLIES	SS	1.00 Shop Supplies	8.95	8.95
			PARTS	13245N	1.00 NEW ALTERNATOR	224.61	224.61
			LABOR		1.60 R & R ALTERNATOR	45.00	72.00
			PARTS	WWS	1.00 WASHER SOLVENT	1.80	1.80
							<u>307.36</u>
4677	03/12/07	196702	A_DIAGNOS	Reported	0.00 DRIVERS DOOR WINDOW OFF TRACK, REAR DOOR NOT OPENING RIGHT, AND DOOR SEAL IS HANGING OUT	0.00	0.00
			SUPPLIES	SS	1.00 Shop Supplies	6.21	6.21
			LABOR		2.60 R & R FRONT WINDOW TRANSMISSION AND REINSTALL LOWER WINDOW TRACK TO THE WINDOW. WE REMOVED THE WEATHER STRIPPING THAT SOME ONE HAD GLUED INTO THE TRACK AT THE FRONT OF THE WINDOW AND INSTALLED THE CORRECT WEATHER STRIPPING THAT HAD PUSHED DOWN INTO THE DOOR.	45.00	117.00
			LABOR		2.00 R & R REAR DOOR HANDLE AND ADJUST LINKAGE, INSTALL NEW WEATHER STRIPPING PUSH PINS AND GLUE THE WEATHER STRIPPING BACK ONTO THE REAR SWING OUT DOOR	45.00	90.00
							<u>213.21</u>
4710	03/19/07	197106	PARTS	99-18	1.00 WIPER BLADE	15.57	15.57
			SUPPLIES	SS	1.00 Shop Supplies	1.50	1.50
			LABOR	LABOR	0.25 REPLACE ONE WIPER BLADE	45.00	11.25
							<u>28.32</u>
5212	08/17/07	208301	LABOR	LOF1	0.45 FULL SERVICE OIL CHANGE	45.00	20.25

- Change Oil
- Replace Oil Filter
- Lubricate Chassis

FOLLOWING ITEMS CHECKED:

- Transmission / Transaxle Fluids
- Differential Fluid
- Brake Fluid
- Power Steering Fluid
- Window Washer Fluid
- Battery Water
- Air Filter
- Breather Element
- Wiper Blade

INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty	Description	Price	Extension
5212		208301	LABOR			- Tire Pressure		
			SUPPLIES	SS	1.00	Shop Supplies	1.67	1.67
			PARTS	51085	1.00	OIL FILTER	7.25	7.25
			PARTS	10001	1.00	OIL ADDITIVE	12.27	12.27
			PARTS	CIT10W30	5.00	10W30 BULK OIL	2.73	13.65
			PARTS	WMS	1.00	WASHER SOLVENT	2.29	2.29
								57.38
5304	09/21/07	210010	A_DIAGNOS	Reported	0.00	THE VAN IS WEARING TIRES	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	44.87	44.87
			PARTS	3087	2.00	SEAL WHEEL BRG	9.41	18.82
			PARTS	ES2121L	1.00	TIE ROD END	18.58	18.58
			PARTS	OS1038S	1.00	ADJUSTING SLEEVE	53.14	53.14
			PARTS	ES2120R	1.00	TIE ROD END	18.58	18.58
			SUBLET	KENNEDY TIRE	1.00	REPLACE 2 UPPER BALL JOINTS THAT WE DO NOT OWN THE TOOLS TO DO, THIS VAN IS ONE OF TWO THAT HAVE THIS TYPE OF JOINTS. ONE CONTROL; ARM NEEDED REPLACING. INSTALL TWO NEW FRONT TIRES AND ALIGHN.	939.19	939.19
			PARTS	EXCISE TAX	2.00	KS EXISE TAX	0.50	1.00
			PARTS	ED315	1.00	DISTRIBUTOR ROTOR	4.70	4.70
			PARTS	FD175	1.00	DISTRIBUTOR CAP	14.03	14.03
			PARTS	4071	8.00	SPARK PLUG	3.55	28.40
			PARTS	82874	1.00	IGNITION/SPARK PLUG WIRE(S)	44.23	44.23
			LABOR		2.00	TUNE UP (MAJOR) INCLUDING ADJUSTMENTS	45.00	90.00
			LABOR		2.40	R & R TIE ROD END (INNER)	50.00	120.00
			LABOR		2.00	R & R TIE ROD END (OUTER)	50.00	100.00
			LABOR	LABOR	1.00	TO KENNEDY TIRE AND BACK	45.00	45.00
								1,540.54
5369	10/05/07	0	FUEL	FUEL	5.50	FUEL FROM TANK	2.75	15.12
			SUPPLIES	SS	1.00	Shop Supplies	1.50	1.50
			A_DIAGNOS	Reported	0.00	SEPT FUEL	0.00	0.00
								16.62
5553	11/28/07	214964	PARTS	51085	1.00	OIL FILTER	7.25	7.25
			SUPPLIES	SS	1.00	Shop Supplies	1.64	1.64
			PARTS	10001	1.00	OIL ADDITIVE	12.27	12.27
			PARTS	CIT10W30	5.00	10W30 BULK OIL	2.73	13.65
			PARTS	WMS	0.50	WASHER SOLVENT	2.29	1.14
			A_DIAGNOS	Reported	0.00	THIS VAN NEEDS NEW MIRRORS, THEY FOLD ON HIM WHILE DRIVING DOWN THE HIGHWAY.	0.00	0.00
			LABOR	LOF1	0.45	FULL SERVICE OIL CHANGE	45.00	20.25
						- Change Oil - Replace Oil Filter - Lubricate Chassis		
						FOLLOWING ITEMS CHECKED:		
						- Transmission / Transaxle Fluids - Differential Fluid - Brake Fluid		

INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty	Description	Price	Extension
5553		214964	LABOR			- Power Steering Fluid - Window Washer Fluid - Battery Water - Air Filter - Breather Element - Wiper Blade - Tire Pressure		
			A_DIAGNOS	Reported	0.00	COOLANT IS GOOD TO -37	0.00	0.00
								56.20
5574	12/04/07	215502	A_DIAGNOS	Reported	0.00	BOTH DOOR MIRRORS ARE FOLDING AT HIGHWAY SPEEDS, THE ADJUSTERS ARE STRIPPED	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	10.99	10.99
			PARTS	55154968	1.00	OUTSIDE DOOR MIRROR	126.98	126.98
			PARTS	55154969	1.00	OUTSIDE DOOR MIRROR	126.98	126.98
			LABOR		1.25	R & R MIRROR (DOOR MOUNTED)	45.00	56.25
			LABOR		1.25	R & R MIRROR (DOOR MOUNTED)	45.00	56.25
								377.45
5895	03/10/08	220733	A_DIAGNOS	Reported	0.00	OIL LEAK	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	4.00	4.00
			PARTS	58707	1.00	TRANS SERVICE KIT	8.68	8.68
			PARTS	32001	4.00	HOSE CLAMP	0.74	2.96
			PARTS	81206	1.00	3/8 POWER STEERING / TRANS COOLER HOSE	2.03	2.03
			PARTS	MULTI-ATF	4.00	MOBIL ONE MULTI VEHICLE ATF	4.63	18.52
			LABOR	LABOR	2.25	SERVICE TRANSMISSION AND REPLACE TRANS COOLER HOSE WITH NEW	45.00	101.25
								137.44
5994	04/04/08	222185	A_DIAGNOS	Reported	0.00	DOOR WILL NOT CLOSE	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	2.73	2.73
			LABOR	LOF1	0.45	FULL SERVICE OIL CHANGE	45.00	20.25
						- Change Oil - Replace Oil Filter - Lubricate Chassis		
						FOLLOWING ITEMS CHECKED:		
						- Transmission / Transaxle Fluids - Differential Fluid - Brake Fluid - Power Steering Fluid - Window Washer Fluid - Battery Water - Air Filter - Breather Element - Wiper Blade - Tire Pressure		
			PARTS	51085	1.00	OIL FILTER	7.25	7.25
			PARTS	10801	1.00	OIL ADDITIVE	11.43	11.43
			PARTS	CT10W30	5.00	10W30 BULK OIL	2.89	14.45
			PARTS	WWS	0.50	WASHER SOLVENT	2.99	1.49
			LABOR	LABOR	0.80	REPLACE MISSING SCREWS FOR THE DOOR LATCH	45.00	36.00

INVOICE HISTORY FOR AIR PRO HEATING & AIR 1997 DODGE TRUCK VAN 1/2 TON VUS 721 #20 2B7HB21Y0

Invoice #	Date	Odometer	Category	Item Number	Qty	Description	Price	Extension
								93.63
6465	08/25/08	225800	A_DIAGNOS	Reported	0.00	THE VAN NEEDS JUMPED TO START AND WILL NOT RUN WITH OUT FOOD ON THE GAS PEDAL	0.00	0.00
			SUPPLIES	SS	1.00	Shop Supplies	2.78	2.78
			PARTS	65-72	1.00	BATTERY	81.44	81.44
			LABOR	BATTERIES	0.25	REPLACE BATTERY WITH NEW. TOO DEAD TO CHARGE.	45.00	11.25
								95.47